



TOOL HOLDERS

An inserted tool bit usually sets in the holder at an angle of from 15° to 20° . In order to grind a front clearance of 5° , one actually grinds an angle of 25° on the part of the tool bit.



Tool bit holders usually hold square, high speed steel bits of various sizes. $\frac{1}{4}$ " x $\frac{1}{4}$ ", $\frac{5}{16}$ " x $\frac{5}{16}$ " and $\frac{3}{8}$ " x $\frac{3}{8}$ " sizes are most common in our shops. The following sketches show some of the standard types of tool holders used in machine shops:

Lathe Tool Holders




Unground Cutter Bits



Knurling Tool Holder



Cutting-Off Tool Holders



Boring Tool Holder









Threading Tool Holder




Boring Tool Holder




 <p>Clearance: Front-10°; Side-10° "Diamond Point" Utility Tool</p>	 <p>Clearance: Front-5°; Side 5° Right-hand Facing Tool</p>	 <p>Clearance: Front-5°; Side 5° Left-hand Facing Tool</p>
 <p>Clearance: Front: 5°; Side-5° Brass & Copper Tool</p>	 <p>Clearance: Front-5°; Side 5° Bull Nose Tool for Cast Iron</p>	 <p>Rake: Back-35°-50°; Side 15° Aluminum Tool</p>


Using the Tool Bit Gage



Testing for Front Clearance,




Side Clearance,




Side Rake

Setting Tool Holder in the Lathe



For straight turning on steel and cast iron, set the cutting edge of the cutter bit, 5° above center of work. Remove burr from cutting edge with a slip stone.



When taper turning, threading or machining brass, set the cutting edge on center.